



National Compressor Services
 10349 Industrial Rd.
 Holland, OH 43528
 Phone: (419)868-4980

Atlanta Office:
 3200 Engineering Parkway
 Alpharetta, GA. 30004
 Phone: (404)410-4055


Texas Office:
 610 North Milby St.
 Houston, TX 77003
 Phone: (337)769-2823

Field Service Report (NCS) - Local_3 Compressor Report

Date: 01/31/2023

CUSTOMER INFORMATION

Date:	01/27/2023
Job#	17384
Master Job Number	OCO1075
Customer:	DTE
Address:	
3500 E. Front Street	
Monroe, MI 48161	
Phone:	(734) 384-2334
Contact:	Tom Tatom
Customer's Email Address:	thomas.tatom@dteenergy.com
Salesman Email Address:	kyle.schock@iss-na.com
PO#	4701756886
Notes:	
Make:	Ingersoll Rand
Model:	Sierra-H150
Serial No.	
Part No.	
Hour Meter:	36965
Size:	150 HP



Name Plate Image



Additional Photo



Additional Photo



National Compressor Services
 10349 Industrial Rd.
 Holland, OH 43528
 Phone: (419)868-4980


Atlanta Office:
 3200 Engineering Parkway
 Alpharetta, GA. 30004
 Phone: (404)410-4055

Texas Office:
 610 North Milby St.
 Houston, TX 77003
 Phone: (337)769-2823


Field Service Report (NCS) - Local_3 Compressor Report

Date: 01/31/2023

Additional Photo



Additional Photo



Additional Photo



Additional Equipment?

No



National Compressor Services
 10349 Industrial Rd.
 Holland, OH 43528
 Phone: (419)868-4980

Atlanta Office:
 3200 Engineering Parkway
 Alpharetta, GA. 30004
 Phone: (404)410-4055

Texas Office:
 610 North Milby St.
 Houston, TX 77003
 Phone: (337)769-2823

Field Service Report (NCS) - Local_3 Compressor Report

Date: 01/31/2023

ADDITIONAL EQUIPMENT #2

Make: _____
 Model: _____
 Serial No. _____
 Part No. _____
 Hour Meter: _____
 Size: _____

ADDITIONAL EQUIPMENT #3

Make: _____
 Model: _____
 Serial No. _____
 Part No. _____
 Hour Meter: _____
 Size: _____

WORK PERFORMED

Was a PM Performed? _____ No

Description of Problem _____
 Unit tripping out on high intercooler pressure.

Service Performed _____

Traveled to site. Spoke with customer found out unit is tripping out on high intercooler pressure immediately. Customer informed me the only way the unit would start would be to remove control line to intercooler pressure transmitter. They also informed me that air was leaking from control line when it was unhooked without unit running, indicating the discharge check valve is leaking. Customer wants quote on new check valve and spare oil filter.

LABOR

Technician	_____	Matt Long
Date	_____	01/27/2023
ST	_____	8
OT	_____	
DT	_____	
Total Hours	_____	8.00

ADDITIONAL WORK NEEDED



National Compressor Services
 10349 Industrial Rd.
 Holland, OH 43528
 Phone: (419)868-4980

Atlanta Office:
 3200 Engineering Parkway
 Alpharetta, GA. 30004
 Phone: (404)410-4055

Texas Office:
 610 North Milby St.
 Houston, TX 77003
 Phone: (337)769-2823

Field Service Report (NCS) - Local_3 Compressor Report

Date: 01/31/2023

Service Complete? No
 Urgent? Yes
 Quote Needed? Yes
 NCS Salesman Email: kyle.schock@iss-na.com
 Email _____
 Notes: _____
 Quote new check valve, gaskets, and spare oil filter.

ADDITIONAL PARTS NEEDED

Part No. 39331038
 Description _____
 Gasket, Flange
 QTY 2

Part No. 24782625
 Description _____
 Check Valve
 QTY 1

Part No. 39911615
 Description _____
 Oil Filter
 QTY 1

SIGNATURE

Customer Signature _____

 Date 01/27/2023

Service Technician Signature _____

 Date 01/27/2023