

# PEVCO Service / PM Form

#### **GENERAL INFORMATION**

Date:	08/07/2023	
Type Of Service:	Service	
GPO Group:	Vizient	
Job Number:	C35005	
Sugar Number:	35488	
Customer P.O. No.:	1234	
Requested By:	John	
Phone Number:	2816447975	
Cell Number:		
Customer Number:	105155	
Customer Name:	MEMORIAL HERMANN	
Customer Street Address:	929 GESSNER RD.	
Customer Street Address 2:	SUITE 1900	
Customer City State, Zip:	HOUSTON, TX 77024	
Bill To:		
Instructions:		
New floor opened up carrier getting lost with missed siting diverter 34		

### SYSTEM INFORMATION

Software Type:	SmartSys
Software Version:	5.5.3.996
Ethernet/Baud Rate:	Ethernet
System Size:	6 Inch
Blowers:	3
Diverters:	19
Stations:	30
Operating System:	Windows 10
Comments:	

### LABOR AND EXPENSE

Date:	08/07/2023
Service Support Representative:	Jeff Heath
Regular Hours:	5
O.T. Hours:	
Holiday Hours:	
Total Regular Labor Charges:	\$970.00
Total O.T. Labor Charges:	\$0.00
Total Holiday Labor Charges:	\$0.00
Total Labor Charges:	\$970.00
EXPENSES:	
Mileage:	62
Mileage Rate:	\$0.85
Parking:	
Tolls:	
Hotel:	
Hotel Receipt:	



1401 Tangier Drive Baltimore, MD 21220 410-931-8800

PEVCO Service / PM Form

Rental Car:	
Rental Car Receipt:	
Air Travel:	
Other:	
Total Expenses:	\$52.70

## SUMMARY & SIGNATURES

Service Support Representative's Report & Recommendations:	
System reset checked history diverter showed siting carri system diverter 34 operating normal	er may be glitch with system monitored
TOTAL MATERIAL:	\$0.00
Total Regular Labor Charges:	\$970.00
Total O.T. Labor Charges:	\$0.00
Total Holiday Charges:	\$0.00
TOTAL EXPENSES:	\$52.70
TOTAL LABOR:	\$970.00
Subtotal (Total Materials Cost + Total Serviceman's	\$1,022.70
Expense):	
Tax Rate:	
Total Tax:	\$0.00
TOTAL BILLING:	\$1,022.70
Pricing is estimated and may change at time of invoice.	
Customer Name:	John Ballantine
Customer's Signature:	
	$\bigcirc$
	XXX A
Date:	08/07/2023
Service Support Representative's Signature:	
	aff the s
Date:	08/07/2023
Dute.	00/07/2025