



No. 1-47454

INVOICE TO:
LETS GET CHECKED
18-45 STEINWAY ST
ASTORIA NY

DATE OF ORDER: 05/21/2024
REFERENCE NO.
CUSTOMER'S ID: LETS GET CHECKED

MAST NUMBER
TRUCK MAKE: TOYOTA
UNIT NUMBER: 058

MODEL: 8HBW23
SERIAL NUMBER: 51532
TRUCK HOUR METER: 721

FINDINGS: - NO WATER IN BATTERIES
REPAIRS MADE: - REMOVED ALL COVER, - CLEANED SERVICE COMPARTMENT, - CLEANED ALL BATTERIES, - WATERED ALL BATTERIES, - BATTERY LOAD TESTED, - PM SERVICE COMPLETED
ADDITIONAL RECOMMENDED REPAIRS:

PARTS

Table with 3 columns: PART No, QTY, DESCRIPTION. Rows include PROWASH and HE-1074.

LABOR

Table with 3 columns: DATE, PERFORMED BY, HOURS. Row for 05/21/2024 by D. MEDINA for 1.00 hours.

The work above has been performed to our satisfaction

Signature fields for Name (GREGG MORAIS), Signature, Date (05/21/2024), Work Order Status (CLOSED), Type of Service (BILLABLE), and Truck Status (IN SERVICE).

PICTURES